


Calorimeter Trigger Tier 1 and Momentum Tree Timing Diagram



In the Col. Trig. Readout_Helpp FPCA, the ERPB Input_Clk ToLk_Clk actually occurs about 20 nsec later, with respect to the 2, and Tier 3 signals, than shown in this diagram.

Because of Cable FanOut and MBD Delays in the Timing & Control Signals to the Calorimeter, the outputs for Tier 1, Tier 2, and Tier 3 actually occur about 50 nsec later, with respect to Sub System Strobe, than shown in this diagram.