

Sputtering Gun & Its Power Supplies Step #3

"Vacuum Space" filled
with low pressure Argon gas

Ar⁺ ions go to
the Target electrode.

Electrons emitted from the
filament go to the Anode.

Electrons from the ionization
of Argon go to grounded
parts of the Gun or to the
grounded Chamber Walls.

