

Fuse Board

Material:
1/4" Linen
Phenolic

Holes:
Drill and
Tap 6-32

Rev.
4-APR-2008

