


SET Curve Tracer - Instrument Amplifier Mounting

Inst Amps Installed



KF Flange & Electrical Feedthrough →

Common Cryo Ground Point ↗

Instrument Amplifiers Mounting Bracket →